The following site is being submitted for inclusion into the GIS registry:

- For DNR County and Region list go to:
 g:\pf\pecfa\site\gis\BRRTS County and Region Codes.xls
- To begin, click on cell to the right of; This is a:
- Use Tab, ↓ or Pg Down to navigate form. Print & include with file when completed.

| | This is a: | New Submittal | | | | | |
|--|--|---|--|--|--|--|--|
| | BRRTS ID (no dashes): | 0341112653 | | | | | |
| | Comm # (no dashes): | 53221340272 | | | | | |
| | County: | Milwaukee | | | | | |
| | Region: | Southeast | | | | | |
| | Site name: | Emjay Station | | | | | |
| | Street Address: | 5072 S 27th St | | | | | |
| | City: | Milwaukee | | | | | |
| | Final Closure Date | 2002-05-24 | | | | | |
| | Closure Conditions: | met | | | | | |
| | Off-source property contamination? | No | | | | | |
| (If yes, attach locational data and deed information on pg. 2) | | | | | | | |
| Right-of-way contamination? | | Yes | | | | | |
| | Contaminated media: | Groundwater | | | | | |
| | GPS Coordinates (meters in the | WTM91 projection) | | | | | |
| | Easting (X): | 687355.000000000 | | | | | |
| | Northing (Y): | 277577.000000000 | | | | | |
| | Collection Method: | Other | | | | | |
| | Scale or Resolution: | 1:4,859 | | | | | |
| (1:24,00 | 00 scale or finer) | finer) ("1:" and comma is default) | | | | | |
| | Prepared by: | Linda Michalets | | | | | |
| | Submitted by: | Cheryl Nelson | | | | | |
| Course | Property Checklist | | | | | | |
| | Final Closure Letter | | | | | | |
| \boxtimes | Copy of the most recent deed, which includes le NR 140 ES | gal description for all properties w/ GW > | | | | | |
| | | R 140 ES here the legal description in the deed(s) refers to a certified survey map or recorded plat | | | | | |
| ∇ | map, include those documents | | | | | | |
| \boxtimes | General Location Map | or all properties w/ GW > NR 140 ES ocation Map | | | | | |
| \boxtimes | Detailed Location Map showing property boundaretc for properties with GW >NR140 ES | aries, buildings, MW(s) and/or potable wells | | | | | |
| \boxtimes | • • | | | | | | |
| | Map showing GW flow direction | • | | | | | |
| \boxtimes | Latest Table of GW results | | | | | | |
| \boxtimes | Geologic cross section (if generated as part of t | - , | | | | | |
| | Statement signed by RP certifying correctness of Updated Database | or legal descriptions | | | | | |

101 West Pleasant Street. Suite 100A

Milwaukee, Wisconsin 53212-3963



Philip Edw. Albert, Secretary



May 24, 2002

Mr. James Sweet Emjay Investments, LLC Two Plaza East, Suite1150 330 East Kilbourn Avenue Milwaukee, WI 53202

RE:

Final Closure

Commerce # 53221-3402-72 WDNR BRRTS # 03-41-112653 Emjay Station, 5072 South 27th Street, Milwaukee

Dear Mr. Sweet:

The Wisconsin Department of Commerce (Commerce) received all the items required as conditions for closure of the above-referenced site. This site is now listed as "closed" on the Commerce database.

It is in your best interest to keep all documentation related to the investigation and remediation of your site. This information may be needed for future property transactions.

If future site conditions indicate that any remaining contamination poses a threat, and subsequent information indicates a need to reopen this case, any original claim under the PECFA fund would also reopen and you may apply for assistance to the extent of remaining eligibility. If contamination is encountered, appropriate measures must be implemented to assure any residual contamination is managed following all applicable State of Wisconsin regulations and standards.

Thank you for your efforts to protect Wisconsin's environment. If you have any questions, please contact me in writing at the letterhead address or by telephone at (414) 220-5376.

Sincerely.

Linda M. Michalets Hydrogeologist Site Review Section

Dr. Pratap N. Singh, K. Singh & Associates, Inc.

Case File

cc:

Document Number

NOTICE OF CONTAMINATION TO PROPERTY

Legal Description of the Property: In re:

(as it appears on the most recent deed)

That part of the South Ten (10) acres of the Northwest One-quarter (1/4) of Section Thirty (30), in Township Six (6) North, Range Twenty-two (22) East, in the City of Milwaukee, County of Milwaukee, State of Wisconsin, bounded and described as follows: Commencing at the South West corner of said Northwest of Section 30-6-22 East; thence East on the South line of said Section, 200.00 feet to a point; thence North and parallel to the West line of said 1/4 Section, 10 rods or 165 feet to a point; thence West on a line which is 10 rods or 165.00 feet North of and parallel to the South line of said 1/2 Section to the West line of said 1/2 Section; thence South on said West line of said 1/4 Section, 10 rods or 165.00 feet to the place of beginning, excepting the West 80 feet thereof. Excepting that part of the Northwest Onequarter (1/4) of Section Thirty (30), in Township Six (6) North, Range Twenty-two (22) East, in the City of Milwaukee, County of Milwaukee, State of Wisconsin, described as follows: Commencing at a point 30 feet North of the South line and 80 feet East of the West line of said 1/4 Section, said point being the point of intersection of the present North line of West Edgerton Avenue and the present East line of South 27th Street; running thence East and parallel to the South line of said 1/4 Section, 120.00 feet to a point; thence North and parallel to the West line of said 1/4 Section, 15.00 feet to a point; thence West and parallel to the South line of said 1/4 Section, 120.00 feet to a point in said East line of South 27th Street; thence South along said East line of South 27th Street, 15.00 feet to the point of commencement.

6218344

REGISTER'S OFFICE | SE Milwankee County, WII RECORDED AT 8:08 AM

(2-05-2002

WALTER R. BARCZAK ABGISTER OF DEEDS

ANUUNY 19.00

2,5

Recording Area

Name and Return Address
James A. Sweet
Emjay Investments, LLC
Two Plaza East - Suite 1150
330 E. Kilbourn Ave.
Milwaukee, WI 53202

623-9653-100-9

Parcel Identif cation Number (PIN)

STATE OF WISCONSIN) ss

COUNTY OF MILWAUKEE

Section 1. <u>EMJAY Investments. LLC</u> is the owner of the above-described property.

Section 2. One or more petroleum discharges have occurred on this property. Groundwater with petroleum contaminant concentrations above NR 140, Wisconsin Administrative Code (Wis. Adm. Code), enforcement standards and soil with contaminant concentrations above NR 720. Wis. Adm. Code, residual contaminant levels are present on the property. A site figure depicting the estimated area of contaminated soil, and tables of soil and groundwater laboratory analytical data are attached.

Section 3. The owner hereby declares that all of the property described above is held and shill be held, conveyed or encumbered, leased, rented, used, occupied and improved subject to the following limitations and/or restrictions:

Anyone who proposes to construct or reconstruct a well on this property is required to contact the Department of Natural Resources' Bureau of Drinking Water and Groundwater, or its successor agency, to determine what specific prohibitions or requirements are applicable, prior to constructing or reconstructing a well on this property. No well may be constructed or reconstructed on this property unless applicable requirements are met.

Residual petroleum contaminated soil remains primarily in the dispenser island areas. It has been shown that the contaminant levels are protective of human health and the environment. If the contaminated soil is excavated in the future, it may be considered a solid waste and must be managed in accordance with all applicable laws.

Any person who is or becomes owner of the property described above may request that the Wisconsin Department of Commerce, or its successor, issue a determination that the restrictions set forth in this covenant are no longer required. That property owner shall provide any and all necessary information to the Department in order for the Department to be able to make

0.0

035

a determination. Upon receipt of such a request, the Department shall determine whether or not the restrictions contained herein can be extinguished. Conditions under which a restriction may be extinguished will be determined in accordance with the site specific standards, rules and laws for this property. If the Department determines that the restrictions can be extinguished, an affidavit, with a copy of the Department's written determination, may be recorded to give notice that this restriction, or portions of this restriction are no longer binding. Any restriction placed upon this property shall not be extinguished without the Department's written determination.

| IN WITNESS WHEREOF, the owner of the property has executed this document, this 18th day of anuary, 2002. | 338 |
|---|----------|
| By signing this document, [he/she] acknowledges that [he/she] is duly authorized to sign this document on behalf of | , |
| Emjay Investments, LLC | S |
| Signature: James a. Aweet | 258 |
| Printed Names JAMES A. SWEET | |
| Title: Member | |
| Subscribed and sworn to before me this 18th day of January , 20 02. | IMAGE |
| Notary Public, State of Wisconsin | 0036 |
| My commission April 4, 2005 | ٠. |

This document was drafted by the Wisconsin Department of Commerce.






Figure 1 – Project Location Map Scale – 1" = 2,000'











Table 1 Groundwater Quality Test Results Emjay Gas Station, 5072 South 27th Street, Milwaukee, WI (Project #4213)

| Well No. | Date | Benzene | Ethylbenzene | Toluene | Xylenes | MTBE | | |
|----------|----------|--------------------------------------|--------------|---------|---------|--------|--|--|
| | | (ppb) | (ppb) | (ppb) | (ppb) | (ppb) | | |
| | | | | | -1.0 | 200 | | |
| MW-1 | 1/6/97 | <0.13 | 0.16 | 0.40 | <1.8 | 390 | | |
| MW-! | 7/17/98 | well damaged during soil remediation | | | | | | |
| MW-1R | 5/26/00 | <0.5 | <0.5 | <0.5 | <0.5 | 539 | | |
| MW-1R | 9/12/00 | <0.5 | <0.5 | <0.5 | <0.5 | 332 | | |
| MW-1R | 12/13/00 | 1.93 | 0.78 | 1.07 | 2.43 | 54.6 | | |
| MW-1R | 3/13/01 | 7.2 | <0.5 | <0.5 | <0.5 | 276 | | |
| MW-1R | 8/3/01 | <0.5 | <0.5 | <0.5 | <0.5 | 182 | | |
| MW-2 | 1/6/97 | <0.13 | 0.41 | 0.17 | <1.8 | 82 | | |
| MW-2 | 7/17/98 | <1.0 | <1.0 | 2.40 | 2.10 | 410 | | |
| MW-2 | 12/30/98 | <0.5 | <0.5 | <0.5 | <0.5 | 830 | | |
| MW-2 | 6/7/99 | < 0.5 | <0.5 | <0.5 | <0.5 | 2900 | | |
| MW-2 | 9/9/99 | 2.6 | <0.22 | 0.28 | <0.23 | 2600 | | |
| MW-2 | 5/26/00 | <0.5 | <0.5 | <0.5 | <0.5 | 5940 | | |
| MW-2 | 9/12/Q0 | <0.5 | <0.5 | <0.5 | <0.5 | 2120 | | |
| MW-2 | 12/13/00 | 0.55 | <0.5 | <0.5 | 1.02 | 1470 | | |
| MW-2 | 3/13/01 | 0.53 | <0.5 | <0.5 | 1.02 | 1600 | | |
| MW-2 | 8/3/01 | <0.5 | <0.5 | <0.5 | <0.5 | 2250 | | |
| MW-3 | 1/6/97 | < 0.13 | 0.14 | 0.05 | <1.8 | 12 | | |
| MW-3 | 7/17/98 | < 0.50 | <0.50 | < 0.50 | < 0.50 | 11 | | |
| MW-3 | 12/30/98 | <0.5 | <0.5 | <0.5 | <0.5 | 4.1 | | |
| MW-3 | 6/7/99 | <0.5 | <0.5 | <0.5 | <0.5 | 3.0 | | |
| MW-3 | 9/9/99 | <0.13 | <0.22 | < 0.2 | < 0.23 | 5.3 | | |
| MW-4 | 1/6/97 | <0.13 | 0.14 | 0.34 | <1.8 | < 0.21 | | |
| MW-4 | 7/17/98 | < 0.50 | <0.50 | <0.50 | < 0.50 | < 0.20 | | |
| MW-4 | 12/30/98 | <0.5 | <0.5 | < 0.5 | <0.5 | <0.2 | | |
| MW-4 | 6/7/99 | <0.5 | <0.5 | <0.5 | <0.5 | < 0.2 | | |
| MW-4 | 9/9/99 | < 0.13 | <0.22 | <0.2 | < 0.23 | < 0.16 | | |
| MW-5 | 1/6/97 | < 0.13 | 0.14 | 0.17 | <1.8 | < 0.21 | | |
| MW-5 | 7/17/98 | < 0.50 | < 0.50 | < 0.50 | < 0.50 | < 0.20 | | |
| MW-5 | 12/30/98 | <0.5 | <0.5 | < 0.5 | <0.5 | < 0.2 | | |
| MW-5 | 6/7/99 | <0.5 | <0.5 | < 0.5 | <0.5 | <0.2 | | |
| MW-5 | 9/9/99 | < 0.13 | <0.22 | <0.2 | < 0.23 | < 0.16 | | |
| MW-6 | 2/3/97 | 0.22 | <0.12 | 0.34 | <1.8 | 11 | | |
| MW-6 | 7/17/98 | < 0.50 | <0.50 | < 0.50 | < 0.50 | 3.2 | | |
| MW-6 | 12/30/98 | <0.5 | <0.5 | <0.5 | <0.5 | 2.8 | | |
| MW-6 | 6/7/99 | <0.5 | <0.5 | <0.5 | <0.5 | 3.4 | | |
| MW-6 | 9/9/99 | <0.13 | <0.22 | <0.2 | <0.23 | 3.2 | | |
| MW-6 | 12/13/00 | <0.5 | <0.5 | <0.5 | <0.5 | 3.36 | | |
| MW-6 | 8/3/01 | <0.5 | <0.5 | <0.5 | <0.5 | 2.95 | | |
| MW-7 | 2/3/97 | <0.13 | <0.12 | 0.16 | <1.8 | <0.21 | | |
| MW-7 | 7/17/98 | <0.50 | <0.50 | < 0.50 | <0.50 | < 0.20 | | |
| MW-7 | 12/30/98 | <0.5 | <0.5 | <0.5 | <0.5 | <0.2 | | |
| MW-7 | 6/7/99 | <0.5 | <0.5 | <0.5 | <0.5 | <0.2 | | |
| MW-7 | 9/9/99 | <0.13 | <0.22 | <0.2 | <0.23 | 3.2 | | |
| MW-7 | 8/3/01 | <0.5 | <0.5 | <0.5 | <0.5 | <0.2 | | |
| PAL | · | 0.5 | 140 | 200 | 1,000 | 12 | | |
| ES | | 5 | 700 | 1,000 | 10,000 | 60 | | |

Note: PAL denotes Preventive Action Limit and ES denotes Enforcement Standards as per NR 140, March 2000









K. SINGH & ASSOCIATES, INC.

Engineers, Scientists and Environmental Management Consultants

RECEIVED

January 16, 2002

Mr. Ronald D. Leonhardt City Clerk, Milwaukee 200 East Wells Street, Room #205 Milwaukee, WI 53202 JAN 1 7 2002

Project #4213

ERS DIVISION MILWAUKEE

Subject:

Information on Groundwater and Soil Contamination at Emjay Station, 5072 South 27th Street, Milwaukee, WI 53221

(COMM #53221-3402-72) (WDNR BRRTS #03-41-112653)

Dear Mr. Leonhardt:

The Wisconsin Department of Commerce has requested that we provide information concerning the groundwater and soil contamination originating from the above referenced site. A layout of the above referenced site is shown on Figure 1. This information is provided to alert you of the potential to come into contact with residual petroleum contaminated groundwater and soil when working on the South 27th Street right-of-way.

The spatial extent of petroleum contamination was delineated through groundwater and soil sampling. Figure 2 provides a plan-view of contours delineating the concentration of methyl tert-butyl ether (MTBE) in parts per billion (ppb) of groundwater sampled in 1997. Groundwater samples collected in September 2001 indicate that the groundwater contamination is confined to the northeastern portion of the property. Table 1 provides information on the residual groundwater contamination. Groundwater flow direction is to the northeast. A contour map of benzene concentration in soil collected in December 1996 and January 1997 is shown on Figure 3. Excavation and off-site bio-remediation of approximately 1,200 tons of contaminated soil was completed in 1998, and Figure 4 shows where the excavation was conducted. Information on residual soil contamination is included in Table 2, which provides soil quality test results for samples collected from the soil borings and the sidewalls and floors of the excavation.

If you have any questions or concerns regarding this submittal, please contact us.

Sincerely,

K. SINGH & ASSOCIATES, INC.

Kristin A. Schultheis Staff Hydrogeologist Pratap N. Singh, Ph.D., P.E.

Ruth N. Sh

Project Manager

Enc: Site Layout (Figure 1)

Contour Map of MTBE Concentration in Groundwater (Figure 2)

Groundwater Quality Test Results (Table 1)

Contour Map of Benzene Concentration in Soil (Figure 3)
Area of Excavation and Residual Soil Contamination (Figure 4)

Summary of Soil Quality Test Results (Table 2)

CC: Jeffrey S. Polenske/City Engineer, Milwaukee

Linda M. Michalets/Department of Commerce Mr. Monte Sweet/Emjay Investments, LLC

Project File